

Company: ERIMSA

Location: Begonte, Spain

Improved cabins of sorting



In terms of safety, Erimsa has maintained a policy that goes beyond the minimum requirements. After improving workplace conditions, Erimsa applies the continuous improvement of methods, especially for exposure to silica dust generated, studying the implementation and monitoring of safety actions and manages to detect, analyse and solve situations that may cause detriment to the workers' safety conditions.